


**Foreshore Taskforce Map 8, 8.1 & 9- Tavistock St-Fraser St Torquay**



[ForeshoreTaskforce-Map8](#)

[Foreshore Taskforce-Map8.1](#)

[Foreshore Taskforce-Map9](#)

Sub-precinct	Key objective	Foreshore Management Unit and objective as per Foreshore Management Plan	Coastal Protection	Vegetation/Embellishments	Recommendation
<p><a href="#">Sub-precinct 15,16, 17, 18 &amp; 19</a></p> 	<p>To enhance the Torquay precinct as a key focus area for passive and active recreation and events by improving visual amenity, community safety and enhanced facilities.</p>	<p><b>Management Unit:</b> Developed parkland <b>Objective:</b></p> <ul style="list-style-type: none"> <li>- Dominant native canopy and shrub vegetation.</li> <li>- Introduced landscape species may be appropriate.</li> <li>- Grassed areas are appropriate.</li> <li>- Revegetation of disturbed areas.</li> <li>- Vegetation planting and management designed to facilitate views through or over vegetation where there will be demonstrable public benefits.</li> </ul> <p><b>Special Vegetation and Foreshore Management</b></p> <ul style="list-style-type: none"> <li>- Enhancement of the natural vegetation communities and habitat either side of Neilsons Park.</li> <li>- Establish and maintain vegetation in the vicinity of the Maryborough Sailing Club so that the area is more visually attractive and free of weeds.</li> <li>- Maintain and enhance foreshore vegetation in the 'Developed Parkland' areas at Torquay so that it is more visually attractive and free from weeds.</li> </ul>	<p>Approved Sandpush area - medium to high priority for active intervention.</p>	<p>High profile passive and active recreation and events area.</p>	<p>Undertake capital works program identified in 2012/13 budget. Crown lift trees. Thin Cottonwoods and crown lift large specimens. Stabilise areas as required through mulching or the planting of ground covers or turf. General tidy up and weed control. Construct disabled beach access. Investigate the provision of: - Decking over stormwater drain outlet. - Decking area in Bill Fraser Park and pedestrian connectivity.</p>